




SHEPPARD

2020401 – REMN - B – VISUAL CORE RETURN GUIDE

Core Return Visual Inspection Guide

Accepted Condition Retainer Nut Installed




Unaccepted Conditions

Retainer Nut Missing



Pitman Arm Installed And \ Or Welded to Sector Shaft*



Gear Disassembled



*Core returns are “like-for-like” if the service gear purchased contains a pitman arm installed at the factory, it will be accepted. Please refer to the RH Sheppard website for additional details and core guidelines.

<https://www.rhsheppard.com/products-services/products/remanufactured-parts/>

R.H. SHEPPARD COMPANY, INC.

101 Philadelphia Street, P.O. Box 877 X Hanover, PA 17331-0877 tel: 717.637.3751 www.rhsheppard.com
Rev B 2025-03-31, Prev 2020201 – REMN - B – CORE RETURN GUIDE



SHEPPARD

For the latest Warranty Policies and Information please check our website at RHSheppard.com or scan the link below.



R.H. SHEPPARD COMPANY, INC.

101 Philadelphia Street, P.O. Box 877 X Hanover, PA 17331-0877 tel: 717.637.3751 www.rhsheppard.com
Rev B 2025-03-31, Prev 2020201 – REMN - B – CORE RETURN GUIDE